


# POWER TOOLS

## PRO 1402 A - MARBLE CUTTER

Packing	Power	Specifications	Mode
6	1200 W	110 MM	COLOR BOX



## PRO 1402 A- MARBLE CUTTER

<b>NO.</b>	<b>Name of Spare parts</b>	<b>NO.</b>	<b>Name of Spare parts</b>
1	Cover Boaro	28	Capacitor
2	Spring Washer 4	29	Self_Lock Dustproof Cover
3	Screw M4 x 20	30	Dustproof Cover For Switch
4	Label	31	Switch
5	Bolt M6 x 18 (left)	32	Small Gear
6	Lock Nut	33	Wind Blocker
7	Blaed	34	Dustproof Ring
8	1 Nner Flange	35	Bearlong 629
9	Frame Dustproof Ring	36	Semicircle Key 2.5 x 10
10	Spindle	37	Armature
11	Semicircle Key	38	Screw ST4.8 x 65
12	Screw M5 x 18	39	Bearing 608
13	Spring Washer 5	40	Stator
14	Bearing 6201	41	Screw ST3x 14
15	Baffle	42	Cord Clip
16	Front Cover	43	Cord Armor
17	Washer For Hole	44	Pull Spring
18	Big Gear	45	Inductance
19	Washer For Spindle	46	Brush Cap
20	Bearing 626	47	Carbon Brush Holder
21	Gear Box	48	Carbon Brush
22	Base Plate parts	49	Name Plate
23	Ringent Spring Pin	50	Housing
24	Flat Washer 6	51	Flat Washer 5
25	Sleeve	52	Screw M5 x 35
26	Bolt m6 x 30	53	Screw ST3.8 x 20
27	Handle Cover	54	Screw M5 x 10
		55	Cord